



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CLIENTE:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

DATA PERIZIA 02/04/2025	LOCALITA' RASOTTO GROUP SRL, Via Flavio Gioia 12, 37135, Verona (VR)																						
VEICOLO (MARCA - MODELLO - VERSIONE) RANGE ROVER SPO 3.0 Sdv6 Mhev 249cv Hse Silver Aut. FP					TARGA GE127SM		TELAIO SALWA2BW4MA783515		1ª IMMATRICOLAZ. 10/03/2021														
KM. 188291	COLORE. Indus Silver			TIPO SMALTO METALL/DOPPIO																			
CODICE PARTE	VOCI DI DANNO LISTINO RICAMBI AGGIORNATO AL	SR		LA		VE		ME		PREZZO LISTINO	DCMS %	RICAMBI IVA esclusa											
		Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO	Diff.	TEMPO														
	presa in carico									0,01		0,01											
	Pneum. post sx Danneggiato																						
	#PRM# Disco ruota anteriore dx danneggiato																						
	#PRM# Disco ruota posteriore sx danneggiato																						
	#PRM# Disco ruota posteriore dx danneggiato																						
	#PRM# Pneumatico post. DX																						
1981	#PRM# Paraurti ant.																						
1918	Parabrezza	S	5,00	S		S				804,78	S17	667,97											
4667	Kit incollaggio cristalli	S		S		S				44,92	S17	37,28											
2187	#PRM# Porta post. SX																						
1945	Parafango post. SX	L	1,00			L	1,10																
1992	#PRM# Paraurti post.																						
2187	Porta post. DX	L	0,65	L	0,85	L	1,35																
TOTALE TEMPI												SR	6,65	LA	0,85	VE	2,45	ME	0,00	TOTALE RICAMBI			705,26
ORE SUPPLEMENTO DOPPIO STRATO 15 %		0,37	ORE SUPPLEMENTO FINITURA 10 % MAX 3 ORE		0,28	ORE AGGIUNTIVE PER VERNICIATURA		1,60	TOTALE ORE SUPPLEMENTARI		2,25	TOTALE ORE VERNICIATURA		4,70									
NOTE Pneumatico ant dx - Continental - 275/45/21 - invernale - 3.9 mm Pneumatico ant sx - Continental - 275/45/21 - invernale - 3.8 mm Pneumatico post dx - Continental - 275/45/21 - invernale - 3.6 mm Pneumatico post sx - Continental - 275/45/21 - invernale - 3.1 mm Ruotino Veicolo sporco esternamente, Periziato con tempo sereno Riserva danni non verificabili in sede di perizia										RICAMBI		705,26											
										MATER. DI CONSUMO		56,40											
										ORE 4,70 €/ORA 12,00													
										USO DIME		0,00											
										SMALTIMENTO RIFIUTI		15,73											
										MANODOPERA CARR.		549,00											
										ORE 12,20 €/ORA 45,00													
										MANODOPERA MECC.		0,00											
										ORE 0,00 €/ORA 45,00													
										IMPONIBILE		1326,39											
										IVA		291,81											
										TOTALE COMPLESSIVO		1618,20											
CODICE PERITO 41	FIRMA			RUOLO N. 0000			FERMO TECNICO GIORNI 2			FOGLIO 1													

Legenda

FF:Forfait

PRM:Promemoria

DE:Difetto esecuzione

GR:Grandine

MAC:Macchiato

NU:Normale usura

SRG:Adesivi



VIA GIULIO PASTORE, 20
10024 MONCALIERI (TO)
Tel. 011 3400911 - Fax 011 3400921
www.dekra-automotivesolutions.com

CUSTOMER:
ALD Automotive Italia S.r.l. a socio unico
VIALE LUCA GAURICO 187
00143 - Roma

APPRAISAL DATE 02/04/2025	LOCATION RASOTTO GROUP SRL, Via Flavio Gioia 12, 37135, Verona (VR)												
VEHICLE (BRAND - MODEL - VERSION) RANGE ROVER SPO 3.0 Sdv6 Mhev 249cv Hse Silver Aut. FP						PLATE GE127SM		CHASSIS SALWA2BW4MA783515		1st REGISTRATION. 10/03/2021			
KM. 188291	COLOR. Indus silver			ENAMEL TYPE Metall/doppio									
PART CODE	ITEMS OF DAMAGE SPARE PARTS LIST UPDATED TO	SR		LA		VE		ME		PRICE LIST	DCMS SPARE PARTS		
		Diff.	TIME	Diff.	TIME	Diff.	TIME	Diff.	TIME		%	VAT excluded	
	Taking charge									0,01		0,01	
	Tire rear left danneggiato												
	#PRM# Right front wheel damaged												
	#PRM# Left rear wheel damaged												
	#PRM# Right rear wheel damaged												
	#PRM# Rear tyre Dx												
1981	#PRM# Front bumper												
1918	Windscreen	S	5,00	S		S				804,78	S17	667,97	
4667	Adhesive bonding kit for screens	S		S		S				44,92	S17	37,28	
2187	#PRM# Rear door Sx												
1945	Rear fender Sx	L	1,00			L	1,10						
1992	#PRM# Rear bumper												
2187	Rear door Dx	L	0,65	L	0,85	L	1,35						
TOTAL TIMES		SR	6,65	LA	0,85	VE	2,45	ME	0,00	TOTAL SPARE PARTS 705,26			
DOUBLE LAYER SUPPLEMENT HOURS 15 %	0,37	FINISHING SUPPLEMENT HOURS 10 % MAX 3 HOURS		0,28	ADDITIONAL HOURS FOR PAINTING		1,60	TOTAL ADDITIONAL HOURS		2,25	TOTAL PAINTING HOURS		4,70
NOTE										SPARE PARTS			705,26
Right front tire - Continental - 275/45/21 - Winter - 3.9 mm										MATER. CONSUMPTION			56,40
Left front tire - Continental - 275/45/21 - Winter - 3.8 mm										HOURS 4,70 €/HOUR 12,00			
Right rear tire - Continental - 275/45/21 - Winter - 3.6 mm										USE TEMPLATES			0,00
Left rear tire - Continental - 275/45/21 - Winter - 3.1 mm										WASTING DISPOSAL			15,73
Spare wheel										LABOR CARR.			549,00
Veicolo sporco esternamente , Appraised in clear weather										HOURS 12,20€/HOUR 45,00			
Riserva danni non verificabili in sede di perizia										LABOR MECH.			0,00
										HOURS 0,00 €/HOUR 45,00			
										TAXABLE			1326,39
										VAT			291,81
										TOTAL			1618,20
EXPERT CODE 41	SIGNATURE				ROLE NUMBER 0000			STOP TECHNICIAN DAYS			2	SHEET 1	

Legend
Ff: forfait Prm: reminder De: lack of execution Gr: hail Mac: stained Nu: normal wear Srg: stickers